

Helicopter Technology Company
12902 South Broadway, Los Angeles, CA 90061 VOICE: 310-523-2750 / FAX: 310-523-2745 www.helicoptertech.com

Issue Date: March 4, 2009

To whom it may concern,

This letter serves to appoint the following company as a:

Helicopter Technology Company (HTC) Factory Authorized Repair Facility

This appointment is applicable for the below listed HTC Part Numbers (P/N's). This document in no way supercedes any regulations or requirements put forth by the Federal Aviation Administration (FAA).

Repair Station: **HeliBlade, Inc.**, FAA Approved Repair Station **#QJZR045Y**
4831 Skyway Drive
Olivehurst, CA 95961
(530) 743-0151 Voice
(530) 743-1391 Fax

HTC P/N's:

500P2100-BSC and -BSC-1 Blade Assembly, Main Rotor
(applicable on 369D, 369E)
500P2100-101, -103, and -105 Blade Assembly, Main Rotor
(applicable on 369D, 369E)
500P2100-301, -303, and -305 Blade Assembly, Main Rotor
(applicable on 369A, 369H, 369HE, 369HM, 369HS)
500P2300-501, -503, and -505 Blade Assembly, Main Rotor
(applicable on 369FF, 500N, 600N)
500P3100-101, -103, and -105 Blade Assembly, Tail Rotor
(applicable on 369D, 369E, 2 Blade Systems)
500P3100-301, -303, and -305 Blade Assembly, Tail Rotor
(applicable on 369D, 369E, 4 Blade Systems)
500P3300-501, -503, and -505 Blade Assembly, Tail Rotor
(applicable on 369A, 369H, 369HE, 369HM, and 369HS)
500P3500-701, -703, and -705 Blade Assembly, Tail Rotor
(applicable on 369FF)

This appointment is valid until revoked by HTC.

Respectfully submitted,

Gary Burdorf
V ice President, Engineering and Quality Assurance