

TECHNICAL BULLETIN

TB 0164

Australmold screened elbow terminations

Issues

Some recently supplied **K430TB18-300-EE01**, (Endeavour Energy stock code 1544188 - Product Approval no. 530108) Australmold screened elbow terminations kits have contained generic instructions (cover page shown in figure 1, below) instead of the Endeavour Energy approved instructions (cover page shown in figure 2 on the following page).


This has caused confusion because the instructions do not match the components supplied.

Additionally, there was no reference to the use of the lime green coloured *cable reducer installation rod*. Page 3 of the termination instructions (shown on the following page) details the installation of the cable reducer with the assistance of lubrication and the *cable reducer installation rod*.

ISS00756-AUS-ENG - 430TB/G-45/LCA

24 July 2013 Revision 0 (Supersedes Euromold edition 14 January 2010 - Revision 7 - Supersedes edition of 23 June 2009)

Page 1 of 8



Australmold are conducting screened elbow product training workshops at the Technical Training Centre – Hoxton Park on Tuesday 30th September 2014. The session times are:

- 9:00am – 11:30am and
- 12:30pm – 3:00pm.

Contact Gabrielle Catulong on 9853 7512 or

galeag@endeavourenergy.com.au to book in for either session.

Figure 1: The cover page of the generic instructions, which should be replaced with the version shown in Figure 2 (shown on the following page) and included in the attached instructions

Contact: Adrian George

Phone: 9853 6198

Date: 26 August 2014

Authorised by: Jude Perera, Manager Primary Systems

51 Huntingwood Drive, Huntingwood NSW 2148

Telephone: 131 081 Fax: (02) 9853 6000

Postal address: PO Box 811 Seven Hills NSW 1730.



Endeavour
Energy

TECHNICAL BULLETIN

TB 0164

Actions

Check that your kit contains the correct instructions and components before beginning the termination and report any discrepancies to the contacts below. Always install the cable reducer as directed in the instructions.




Figure 2 above left: The cover page of the Endeavour Energy approved termination instructions




Figure 3 above right: The use of the lubricated installation rod enables the cable reducer to be installed correctly onto the core




Figure 4 at left: The correct cable reducer and installation rod

Contact: Adrian George

Phone: 9853 6198

Date: 26 August 2014

Authorised by: Jude Perera, Manager Primary Systems

51 Huntingwood Drive, Huntingwood NSW 2148
Telephone: 131 081 Fax: (02) 9853 6000
Postal address: PO Box 811 Seven Hills NSW 1730.

