


RELEASE NOTES

	Product	Version	Release Date	Changes	Descriptions
	SPS	3.01	5/7/2013	Bug Fixes	<ul style="list-style-type: none"> Fixes undesired power down of the sensor pack by the debounce routines monitoring the sensor power line