



Endeavour Energy



A message from

Customer Network Solutions

16/2025

Temporary Issue with Underground Data Display in ASP ESRI Map


We're currently aware of an issue affecting the display of underground network data in the ASP ESRI Map. While this information isn't visible in the app at the moment, please be assured that all underground data is still included in any CAD extracts for the affected areas.

A fix is underway, and we expect it to be resolved within approximately two weeks.

If you need more information or support in the meantime, feel free to contact us at MOCS@endeavourenergy.com.au.

Example: O'Dell Street Vineyard

ASP ESRI Map



CAD Extract



Kind regards,

Customer Network Solutions