

Harbourside Redevelopment (SSD 7974) Issues Register

In accordance with B5 (a) (Viii) of the <u>Harbourside Redevelopment SSD 7874 Conditions of Consent</u> this register is to be updated monthly and uploaded onto the project website until the completion of all works under the Conditions consent.

Updated: 31 May 2023

Date of Issue	Enquirer Category	Nature of Issue	Response	Status
	Government	Called on behalf of a constituent (a local resident) raising concerns about dust control measures. The constituents' dust allergies have been exacerbated by construction works.	Dust mitigation measures include localised dust suppression activity including pre-wetting of the areas of activity and materials handling and a localised misting system Air quality/dust monitors are installed in nominated locations in accordance with the Air Quality Management Plan and Demolition Management Plan Reports from the period of concern all recorded dust levels well below the maximum allowable concentration criteria in the NSW EPA guidelines.	
12/05/2023	Local resident	Concerns relating to proper enforcement of dust mitigation measures by contractors on site.	Dust mitigation measures include localised dust suppression activity including pre-wetting of the areas of activity and materials handling and a localised misting system Air quality/dust monitors are installed in nominated locations in accordance with the Air Quality Management Plan and Demolition Management Plan Reports from the period of concern all recorded dust levels well below the maximum allowable concentration criteria in the NSW EPA guidelines.	
17/05/2023	Neighbouring landowner	Concerns relating to dust from the construction site coming into the organisation and impacts to operations.	Dust mitigation measures include localised dust suppression activity including pre-wetting of the areas of activity and materials handling and a localised misting system Air quality/dust monitors are installed in nominated locations in accordance with the Air Quality Management Plan and Demolition Management Plan Reports from the period of concern all recorded dust levels well below the maximum allowable concentration criteria in the NSW EPA guidelines.	