

# Temporary Closure: Refurbishment at Existing Buildings

## **Refurbishment & Construction Work**

The construction industry has been rapidly ramping up preparations to deal with the coronavirus. Our customers are facing enormous challenges as buildings undergoing refurbishment are forced to close or operate on a limited basis as workplaces shutdown or shift to homeworking. This could lead to some construction sites being minimally occupied for example, safety critical trades may continue or, in the worst-case scenario, long term site shutdowns.

We've put together a checklist of risk control measures to consider in order to help secure buildings undergoing a full or partial refurbishment, extension or undergoing major maintenance work and to use as a reference point for regular checks during temporary closedown periods. This guidance is from a risk management perspective only. Any queries relating to insurance cover should be made with your insurance advisor or broker.

### **Risk Control Measures**

- **Sprinkler Impairment**: If your building has a sprinkler system, contractors may have isolated part of the system. Any sprinkler system needs to be reinstated prior to the site being vacated. A robust check needs to be made sure that all parts of the sprinkler system, including all isolated valves, have been left open.
- **Sprinkler Notification**: Please note that Zurich need to be notified of any sprinkler impairment through our Impairment Reporting System which also contains detailed risk management guidance on the topic.
- **Automatic fire detection**: Ensure that fire detection systems have been reinstated. Work with the contractor to ensure that dust caps to smoke/heat detectors have been removed.
- **Hot Work**: The emergency services may be strained at this time. Therefore, high risk activities such as hot work should be avoided or changed to lower risk alternatives. Please note, hot work must not be undertaken if you have isolated the sprinkler system.
- **Hot Work Permit**: If hot work needs to continue, please ensure a task area risk assessment is completed, a Hot Work Permit is issued and named fire watchers are provided.
- **Site security:** Work with your contractor to ensure that the site has been left in a safe manner e.g. your building security has not been compromised e.g. no unsecured access into the building via scaffolding **Combustible materials and waste:** If you have experienced recent thefts, malicious damage or squatting issues please contact Zurich for guidance. **Combustible materials and waste:** Make sure combustible materials and waste have been removed from site. Ensure that skips are emptied and stored 10 metres from the building. If this cannot be achieved, please provide locked metal containers and locked skips.

### Other Considerations:

- We have produced separate guides for temporarily closed buildings, schools, and construction sites.
- Please ensure that you comply with existing government guidance regarding vulnerable people and lone worker risk assessments. Consider the provisioning for alternative skilled personnel.
- Ensure that remaining site staff include trained fire wardens, and knowledge of the action to take in the event of an emergency.
- If you have experienced any recent thefts, malicious damage or other incidents please contact Zurich for guidance.

# **Temporary Construction Site Closure Checklist**

Site checks					
Ensure the sprinkler system, and any locally solated valves, is fully reinstated.	Yes		No		Date:
Notify Zurich of any sprinkler impairment through our <u>Impairment Reporting System</u>	Yes	•	No	•	Date:
Ensure fire detection systems are reinstated and any dust caps in contractor-controlled areas are removed.	Yes		No		Date:
Any flammables and pressurized gas cylinders are removed from site	Yes	•	No	•	Date:
Any planned hot work activities be delayed or switched to lower risk alternatives	Yes	•	No	•	Date:
Hot work permit procedures strictly are adhered to	Yes	•	No	•	Date:
Confirm with your contractor any required safety inspections e.g. scaffold inspection, post-adverse weather site inspection	Yes	•	No	•	Date:
f the site is provided with existing manned guarding e.g. overnight, weekend or security patrols, there is an expectation that this continues	Yes	•	No	•	Date:
Non-essential building utilities, temporary or permanent, and equipment in the site area have been safety isolated. No charging left on.	Yes	•	No	•	Date:
Valuable contents, hired-in plant or machinery has been removed from site or securely stored	Yes	•	No	•	Date:
Site hoarding is complete and in good condition	Yes	•	No	•	Date:
Access from the site area into the building is secure	Yes	•	No	•	Date:
Security intruder alarm and/or scaffold alarm is working correctly and activated whenever the building is secured including any remote signalling	Yes	•	No	•	Date:
Security keyholder response is update and adequately resourced	Yes	•	No	•	Date:
External lighting is operational	Yes		No		Date:
CCTV is operational with adequate lighting	Yes	•	No	•	Date:

### Important Notice:

Only you can make your workplace safe. Any risk management duties of your company cannot be delegated and Zurich Australian Insurance Ltd ABN 13 000 296 640 or any of its affiliated companies (hereinafter 'Zurich') accepts no delegation and cannot assume any of those risk management duties and/or decisions. Zurich will assist you by providing the specific risk management consulting and services for which you have contracted. Zurich makes no warranties in conjunction with those services, and it undertakes no obligations other than as set out in the contract.

All information contained in this document has been compiled and obtained from sources believed to be reliable and credible but no representation or warranty, express or implied, is made by Zurich as to their accuracy or completeness. Some of the information contained herein may be time sensitive. Thus, you should consult the most recent referenced material.

We understand that some of the advice given in this document may be impractical due to ever-changing circumstances and government advice or restrictions. Some advice may not apply to your circumstances. We have attempted to provide as much succinct advice as quickly as we could to assist you.

Information relating to risk services is intended as a general description of certain types of risk and/or risk mitigation services available to qualified customers. Zurich and its employees do not assume any liability of any kind whatsoever, resulting from the use, or reliance upon any information, material or procedure contained herein. Zurich and its employees do not guarantee particular outcomes and there may be conditions on your premises or within your organization which may not be apparent to us. You are in the best position to understand your business and your organization and to take steps to minimize risk, and we wish to assist you by providing the information and tools to assess your changing risk environment.

Confidential: For questions related to the duplication or distribution of this document, please contact your Zurich representative. Copyright © 2020 Zurich LWIN-015435-2020