

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1020/1021**  
Number of samples: 1  
Samples received: 29-04-2024  
Report date: 02-05-2024  
Report no.: 79966 ~

Sampling start:	29-04-2024 kl.08:45	Laboratory no.:	DV24170391-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>ZN1 1020/1021</b>
Analysis period:	29-04-2024 to 02-05-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51:, Flow Bench</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>12,5</b>	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow  
bench ZN1 1020/1021**

Number of samples: 1

Samples received: 29-04-2024

Report date: 02-05-2024

Report no.: 79966 ~

---

**The report will be sent by email to:**

vandanalysedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**

None

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1022/1023**  
Number of samples: 1  
Samples received: 29-04-2024  
Report date: 02-05-2024  
Report no.: 79969 ~

Sampling start:	29-04-2024 kl.08:47	Laboratory no.:	DV24170393-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>ZN1 1022/1023</b>
Analysis period:	29-04-2024 to 02-05-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>16,3</b>	°C		0	SM 2550:2005, Felt	d
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

- d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428
- h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow  
bench ZN1 1022/1023**

Number of samples: 1

Samples received: 29-04-2024

Report date: 02-05-2024

Report no.: 79969 ~

---

**The report will be sent by email to:**

vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**

None

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1024/1025**  
Number of samples: 1  
Samples received: 29-04-2024  
Report date: 02-05-2024  
Report no.: 79971 ~

Sampling start:	29-04-2024 kl.08:50	Laboratory no.:	DV24170394-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>ZN1 1024/1025</b>
Analysis period:	29-04-2024 to 02-05-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>15,3</b>	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

## ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow  
bench ZN1 1024/1025**

Number of samples: 1

Samples received: 29-04-2024

Report date: 02-05-2024

Report no.: 79971 ~

---

**The report will be sent by email to:**

vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**

None

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1026/1027**  
Number of samples: 1  
Samples received: 29-04-2024  
Report date: 02-05-2024  
Report no.: 79974 ~

Sampling start:	29-04-2024 kl.08:52	Laboratory no.:	DV24170395-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>ZN1 1026/1027</b>
Analysis period:	29-04-2024 to 02-05-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>14,4</b>	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow  
bench ZN1 1026/1027**

Number of samples: 1

Samples received: 29-04-2024

Report date: 02-05-2024

Report no.: 79974 ~

---

**The report will be sent by email to:**

vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**

None

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - 1032**  
Number of samples: 1  
Samples received: 29-04-2024  
Report date: 02-05-2024  
Report no.: 79981 ~

Sampling start:	29-04-2024 kl.08:59	Laboratory no.:	DV24170398-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>1032</b>
Analysis period:	29-04-2024 to 02-05-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	17,3	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	0	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	0,24 (lg)
Coliform bacteria	0	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)
Escherichia coli (E.coli)	0	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	h 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

## ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - 1032**  
Number of samples: 1  
Samples received: 29-04-2024  
Report date: 02-05-2024  
Report no.: 79981 ~

---

**The report will be sent by email to:**

vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**

None

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .