

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1020/1021**  
Number of samples: 1  
Samples received: 24-06-2024  
Report date: 27-06-2024  
Report no.: 83706 ~

Sampling start:	24-06-2024 kl.07:40	Laboratory no.:	DV24230166-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>ZN1 1020/1021</b>
Analysis period:	24-06-2024 to 27-06-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>15,6</b>	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

#### Location reference:

- h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428
- d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Helle Møllegård Dahl  
Teamleder Vand & Speciale

#### Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

## ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow  
bench ZN1 1020/1021**

Number of samples: 1

Samples received: 24-06-2024

Report date: 27-06-2024

Report no.: 83706 ~

---

**The report will be sent by email to:**

vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**

None

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1022/1023**  
Number of samples: 1  
Samples received: 24-06-2024  
Report date: 27-06-2024  
Report no.: 83712 ~

Sampling start:	24-06-2024 kl.07:44	Laboratory no.:	DV24230167-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>ZN1 1022/1023</b>
Analysis period:	24-06-2024 to 27-06-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>13,7</b>	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

#### Location reference:

- h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428
- d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Helle Møllegård Dahl  
Teamleder Vand & Speciale

#### Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow  
bench ZN1 1022/1023**

Number of samples: 1

Samples received: 24-06-2024

Report date: 27-06-2024

Report no.: 83712 ~

---

**The report will be sent by email to:**

vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**

None

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1024/1025**  
Number of samples: 1  
Samples received: 24-06-2024  
Report date: 27-06-2024  
Report no.: 83738 ~

Sampling start:	24-06-2024 kl.07:48	Laboratory no.:	DV24230169-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>ZN1 1024/1025</b>
Analysis period:	24-06-2024 to 27-06-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>16,3</b>	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

#### Location reference:

- h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428
- d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Helle Møllegård Dahl  
Teamleder Vand & Speciale

#### Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1024/1025**  
Number of samples: 1  
Samples received: 24-06-2024  
Report date: 27-06-2024  
Report no.: 83738 ~

**The report will be sent by email to:**  
vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**  
None

## Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1026/1027**  
Number of samples: 1  
Samples received: 24-06-2024  
Report date: 27-06-2024  
Report no.: 83741 ~

Sampling start:	24-06-2024 kl.07:52	Laboratory no.:	DV24230170-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>ZN1 1026/1027</b>
Analysis period:	24-06-2024 to 27-06-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>14,6</b>	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

- h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428
- d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Helle Møllegård Dahl  
Teamleder Vand & Speciale

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow  
bench ZN1 1026/1027**

Number of samples: 1

Samples received: 24-06-2024

Report date: 27-06-2024

Report no.: 83741 ~

---

**The report will be sent by email to:**  
vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**  
None

## Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - 1032**  
Number of samples: 1  
Samples received: 24-06-2024  
Report date: 27-06-2024  
Report no.: 83750 ~

Sampling start:	24-06-2024 kl.08:02	Laboratory no.:	DV24230173-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>1032</b>
Analysis period:	24-06-2024 to 27-06-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>18,5</b>	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

#### Location reference:

- h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428
- d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Helle Møllegård Dahl  
Teamleder Vand & Speciale

#### Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

## ANALYSIS REPORT

Kamstrup A/S  
Industrivej 28  
8660 Skanderborg

Case name: **Kamstrup - 1032**  
Number of samples: 1  
Samples received: 24-06-2024  
Report date: 27-06-2024  
Report no.: 83750 ~

---

**The report will be sent by email to:**

vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**

None

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - 1031**  
Number of samples: 1  
Samples received: 24-06-2024  
Report date: 28-06-2024  
Report no.: 83788 ~

Sampling start:	24-06-2024 kl.08:10	Laboratory no.:	DV24230174-001
Sampler:	Højvang/JTO	<b>Sample ID:</b>	<b>1031</b>
Analysis period:	24-06-2024 to 28-06-2024	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458: 2006 + MST Drinking water. Manual for sampling: 2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	17,8	°C		0	SM 2550:2005, Felt	h
Pseudomonas aeruginosa	0	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	0	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	0	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

- h) Højvang Laboratorier A/S, Holstebro. DANAK-Nr.: 428
- d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 529 of 14/05/2023 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Helle Møllegård Dahl  
Teamleder Vand & Speciale

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - 1031**  
Number of samples: 1  
Samples received: 24-06-2024  
Report date: 28-06-2024  
Report no.: 83788 ~

---

**The report will be sent by email to:**

vandanalsedk@kamstrup.com - Vandanalyser

**Appendices for this report:**

None

Report status: Replacement

This report replaces: 83755

Reason for change: IT change

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .