

Kamstrup A/S  
Industrivej 28  
8660 Skanderborg

Case name: **Kamstrup - Flow bench ZN1 1020/1021**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120346 ~

Sampling start:	24-11-2025 kl.08:14	Laboratory no.:	DV25440055-001
Sampler:	Højvang/fko	<b>Sample ID:</b>	<b>ZN 1 1020/1021</b>
Analysis period:	24-11-2025 to 27-11-2025	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458:2006 + MST Drikkevand. Manual for prøvetagning:2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>17,0</b>	°C		0	SM 2550:2005, Felt	s
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety. Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

## ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow  
bench ZN1 1020/1021**

Number of samples: 1

Samples received: 24-11-2025

Report date: 27-11-2025

Report no.: 120346 ~

**The report will be sent by email to:**  
vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**  
None

### Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1022/1023**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120348 ~

Sampling start:	24-11-2025 kl.08:20	Laboratory no.:	DV25440057-001
Sampler:	Højvang/fko	<b>Sample ID:</b>	<b>ZN 1 1022/1023</b>
Analysis period:	24-11-2025 to 27-11-2025	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458:2006 + MST Drikkevand. Manual for prøvetagning:2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>16,5</b>	°C		0	SM 2550:2005, Felt	s
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

## ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1022/1023**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120348 ~

**The report will be sent by email to:**  
vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**  
None

### Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1024/1025**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120350 ~

Sampling start:	24-11-2025 kl.08:24	Laboratory no.:	DV25440058-001
Sampler:	Højvang/fko	<b>Sample ID:</b>	<b>ZN 1 1024/1025</b>
Analysis period:	24-11-2025 to 27-11-2025	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458:2006 + MST Drikkevand. Manual for prøvetagning:2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>18,7</b>	°C		0	SM 2550:2005, Felt	s
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety. Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1024/1025**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120350 ~

**The report will be sent by email to:**  
vandanalsedk@kamstrup.com - Vandanalyser

**Appendices for this report:**  
None

Report status: Final

## Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1026/1027**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120352 ~

Sampling start:	24-11-2025 kl.08:28	Laboratory no.:	DV25440059-001
Sampler:	Højvang/fko	<b>Sample ID:</b>	<b>ZN 1 1026/1027</b>
Analysis period:	24-11-2025 to 27-11-2025	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458:2006 + MST Drikkevand. Manual for prøvetagning:2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>18,4</b>	°C		0	SM 2550:2005, Felt	s
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety. Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench ZN1 1026/1027**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120352 ~

**The report will be sent by email to:**  
vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**  
None

## Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench 1032**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120358 ~

Sampling start:	24-11-2025 kl.08:33	Laboratory no.:	DV25440060-001
Sampler:	Højvang/fko	<b>Sample ID:</b>	<b>1032</b>
Analysis period:	24-11-2025 to 27-11-2025	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458:2006 + MST Drikkevand. Manual for prøvetagning:2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>18,9</b>	°C		0	SM 2550:2005, Felt	s
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety. Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

# ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench 1032**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120358 ~

**The report will be sent by email to:**  
vandanalsedk@kamstrup.com - Vandanalyser

Report status: Final

**Appendices for this report:**  
None

## Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench 1031**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120360 ~

Sampling start:	24-11-2025 kl.08:41	Laboratory no.:	DV25440061-001
Sampler:	Højvang/fko	<b>Sample ID:</b>	<b>1031</b>
Analysis period:	24-11-2025 to 27-11-2025	Packaging:	OK
Sampling point:	<b>Kamstrup industrivej 28 / 51.;</b>	Purpose:	Operational control
Sample type:	<b>Process water (analyzed as drinking water)</b>	Scope:	Microbiological control
Withdrawal method:	Random sample		

Sampling method: ISO 19458:2006 + MST Drikkevand. Manual for prøvetagning:2021

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	<b>18,2</b>	°C		0	SM 2550:2005, Felt	s
Pseudomonas aeruginosa	<b>0</b>	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	<b>0</b>	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

**Exceedances:** No exceedances, cf. the min. / Max. Values specified in the report

**Deviations / comments for this test:** None

**Location reference:**

d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety. Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.

Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.

Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.

Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.

Made according to:

BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

**Approved by:**



Gitte Pedersen  
Laborant

**Designations:**

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number.

## ANALYSIS REPORT

**Kamstrup A/S**  
**Industrivej 28**  
**8660 Skanderborg**

Case name: **Kamstrup - Flow bench 1031**  
Number of samples: 1  
Samples received: 24-11-2025  
Report date: 27-11-2025  
Report no.: 120360 ~

**The report will be sent by email to:**  
vandanalsedk@kamstrup.com - Vandanalyser

**Appendices for this report:**  
None

Report status: Final

### Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.

\* Not accredited.

# Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.

^ Analyzed for quality requirements for environmental measurements

~ This is a translation of the Danish report with the same report number .