ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench ZN1 1020/1021**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101011 ~

Sampling start:	24-03-2025 kl.07:53	Laboratory no.:	DV25100260-001
Sampler:	Højvang/SRI	**Sample ID:**	**ZN1 1020/1021**
Analysis period:	24-03-2025 19:15:47 to 27-03-2025	Packaging:	OK
Sampling point:	**Kamstrup industrivej 28 / 51:,**	Purpose:	Operational control
Sample type:	**Process water (analyzed as drinking water)**	Scope:	Microbiological control
Withdrawal method:	Random sample		
Sampling method:	ISO 19458:2006 + MST Drikkevand. Manual for prø vetagning:2021		

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	**16,4**	°C		0	SM 2550:2005, Felt	f
Pseudomonas aeruginosa	**0**	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

Exceedances: No exceedances, cf. the min. / Max. Values specified in the report

Deviations / comments for this test: None

Location reference:

f) Højvang Laboratorier A/S, Fredericia. DANAK no.: 428
d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety
Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.
Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.
Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.
Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.
Made according to:
BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

Approved by:

Helle Møllegård Dahl
Teamleder Vand & Speciale

Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench ZN1 1020/1021**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101011 ~

The report will be sent by email to:
vandanalysedk@kamstrup.com - Vandanalyser

Report status: Final

Appendices for this report:
None

Designations:
+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench ZN1 1022/1023**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101015 ~

Sampling start:	24-03-2025 kl.07:57	Laboratory no.:	DV25100261-001
Sampler:	Højvang/SRI	**Sample ID:**	**ZN1 1022/1023**
Analysis period:	24-03-2025 19:15:48 to 27-03-2025	Packaging:	OK
Sampling point:	**Kamstrup industrivej 28 / 51:,**	Purpose:	Operational control
Sample type:	**Process water (analyzed as drinking water)**	Scope:	Microbiological control
Withdrawal method:	Random sample		
Sampling method:	ISO 19458:2006 + MST Drikkevand. Manual for prø vetagning:2021		

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	**18,7**	°C		0	SM 2550:2005, Felt	f
Pseudomonas aeruginosa	**0**	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

Exceedances: No exceedances, cf. the min. / Max. Values specified in the report

Deviations / comments for this test: None

Location reference:

f) Højvang Laboratorier A/S, Fredericia. DANAK no.: 428
d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety
Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.
Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.
Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.
Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.
Made according to:
BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

Approved by:

Helle Møllegård Dahl
Teamleder Vand & Speciale

Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench ZN1 1022/1023**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101015 ~

The report will be sent by email to:
vandanalysedk@kamstrup.com - Vandanalyser

Report status: Final

Appendices for this report:
None

Designations:
+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench ZN1 1024/1025**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101019 ~

Sampling start:	24-03-2025 kl.08:00	Laboratory no.:	DV25100262-001
Sampler:	Højvang/SRI	**Sample ID:**	**ZN1 1024/1025**
Analysis period:	24-03-2025 19:15:49 to 27-03-2025	Packaging:	OK
Sampling point:	**Kamstrup industrivej 28 / 51:,**	Purpose:	Operational control
Sample type:	**Process water (analyzed as drinking water)**	Scope:	Microbiological control
Withdrawal method:	Random sample		
Sampling method:	ISO 19458:2006 + MST Drikkevand. Manual for prø vetagning:2021		

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	**15,7**	°C		0	SM 2550:2005, Felt	f
Pseudomonas aeruginosa	**0**	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

Exceedances: No exceedances, cf. the min. / Max. Values specified in the report

Deviations / comments for this test: None

Location reference:

f) Højvang Laboratorier A/S, Fredericia. DANAK no.: 428
d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety
Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.
Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.
Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.
Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.
Made according to:
BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

Approved by:

Helle Møllegård Dahl
Teamleder Vand & Speciale

Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench ZN1 1024/1025**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101019 ~

The report will be sent by email to:
vandanalysedk@kamstrup.com - Vandanalyser

Report status: Final

Appendices for this report:
None

Designations:
+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench ZN1 1026/1027**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101023 ~

Sampling start:	24-03-2025 kl.08:03	Laboratory no.:	DV25100263-001
Sampler:	Højvang/SRI	**Sample ID:**	**ZN1 1026/1027**
Analysis period:	24-03-2025 19:15:49 to 27-03-2025	Packaging:	OK
Sampling point:	**Kamstrup industrivej 28 / 51:,**	Purpose:	Operational control
Sample type:	**Process water (analyzed as drinking water)**	Scope:	Microbiological control
Withdrawal method:	Random sample		
Sampling method:	ISO 19458:2006 + MST Drikkevand. Manual for prø vetagning:2021		

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	**15,2**	°C		0	SM 2550:2005, Felt	f
Pseudomonas aeruginosa	**0**	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

Exceedances: No exceedances, cf. the min. / Max. Values specified in the report

Deviations / comments for this test: None

Location reference:

f) Højvang Laboratorier A/S, Fredericia. DANAK no.: 428
d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety
Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.
Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.
Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.
Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.
Made according to:
BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

Approved by:

Helle Møllegård Dahl
Teamleder Vand & Speciale

Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench ZN1 1026/1027**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101023 ~

The report will be sent by email to:
vandanalysedk@kamstrup.com - Vandanalyser

Report status: Final

Appendices for this report:
None

Designations:
+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench 1032**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101027 ~

Sampling start:	24-03-2025 kl.08:07	Laboratory no.:	DV25100266-001
Sampler:	Højvang/SRI	**Sample ID:**	**1032**
Analysis period:	24-03-2025 19:15:50 to 27-03-2025	Packaging:	OK
Sampling point:	**Kamstrup industrivej 28 / 51:,**	Purpose:	Operational control
Sample type:	**Process water (analyzed as drinking water)**	Scope:	Microbiological control
Withdrawal method:	Random sample		
Sampling method:	ISO 19458:2006 + MST Drikkevand. Manual for prø vetagning:2021		

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	**18,5**	°C		0	SM 2550:2005, Felt	f
Pseudomonas aeruginosa	**0**	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

Exceedances: No exceedances, cf. the min. / Max. Values specified in the report

Deviations / comments for this test: None

Location reference:

f) Højvang Laboratorier A/S, Fredericia. DANAK no.: 428
d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety
Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.
Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.
Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.
Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.
Made according to:
BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

Approved by:

Helle Møllegård Dahl
Teamleder Vand & Speciale

Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench 1032**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101027 ~

The report will be sent by email to:
vandanalysedk@kamstrup.com - Vandanalyser

Report status: Final

Appendices for this report:
None

Designations:
+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench 1031**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101032 ~

Sampling start:	24-03-2025 kl.08:10	Laboratory no.:	DV25100267-001
Sampler:	Højvang/SRI	**Sample ID:**	**1031**
Analysis period:	24-03-2025 19:15:50 to 27-03-2025	Packaging:	OK
Sampling point:	**Kamstrup industrivej 28 / 51:,**	Purpose:	Operational control
Sample type:	**Process water (analyzed as drinking water)**	Scope:	Microbiological control
Withdrawal method:	Random sample		
Sampling method:	ISO 19458:2006 + MST Drikkevand. Manual for prø vetagning:2021		

Parameter	Result	Unit	Min / Max.	DL	References	+/-
Temperature	**18,2**	°C		0	SM 2550:2005, Felt	f
Pseudomonas aeruginosa	**0**	CFU/100 mL	/ 0	0	ISO 16266:2008+MM0014^	d 0,24 (lg)
Coliform bacteria	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)
Escherichia coli (E.coli)	**0**	MPN/100 mL	/ < 0	0	DS/EN ISO 9308-2:2014+MM0001^	d 0,25 (lg)

Exceedances: No exceedances, cf. the min. / Max. Values specified in the report

Deviations / comments for this test: None

Location reference:

f) Højvang Laboratorier A/S, Fredericia. DANAK no.: 428
d) Højvang Laboratories A/S, Dianalund. DANAK no.: 428

The test results only apply to the tested items / subsets. Without the written permission of the laboratory, the report may only be reproduced in its entirety
Højvang Laboratorier A/S disclaims any responsibility in connection with data provided by the requester.
Højvang Laboratorier A/S refuses to comment on attitudes and interpretations.
Analysis results are stated in the report with 2 significant digits unless otherwise agreed. When comparing with any limit and / or requirement value, the analysis result is used in the report.
Højvang Laboratorier A/S disclaims any responsibility in connection with the use of the stated minimum and maximum values or the use of the classifications made.
Made according to:
BEK no. 811 of 27/06/2024 Executive Order on quality requirements for environmental measurements

The sample has been taken in accordance with the current sampling plan / agreement.

Approved by:

Helle Møllegård Dahl
Teamleder Vand & Speciale

Designations:

+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .

ANALYSIS REPORT

Kamstrup A/S
Industrivej 28
8660 Skanderborg

Case name:	**Kamstrup - Flow bench 1031**
Number of samples:	1
Samples received:	24-03-2025
Report date:	27-03-2025
Report no.:	101032 ~

The report will be sent by email to:
vandanalysedk@kamstrup.com - Vandanalyser

Report status: Final

Appendices for this report:
None

Designations:
+/- expanded relative uncertainty in% with coverage factor 2. Results at the detection limit level are subject to a relatively greater measurement uncertainty than is generally the case.
Symbolizes that all components included in the sum in question have a concentration less than the detection limit of the individual component.
^ Analyzed for quality requirements for environmental measurements
~ This is a translation of the Danish report with the same report number .